

ASME B5.57-2012
[Revision of ASME B5.57-1998 (R2006)]

Methods for Performance Evaluation of Computer Numerically Controlled Lathes and Turning Centers

AN AMERICAN NATIONAL STANDARD



**The American Society of
Mechanical Engineers**

ASME B5.57-2012
[Revision of ASME B5.57-1998 (R2006)]

Methods for Performance Evaluation of Computer Numerically Controlled Lathes and Turning Centers

AN AMERICAN NATIONAL STANDARD



**The American Society of
Mechanical Engineers**

Two Park Avenue • New York, NY • 10016 USA

Date of Issuance: May 3, 2013

This Standard will be revised when the Society approves the issuance of a new edition. There will be no written interpretations of the requirements of this Standard issued to this edition.

Periodically, certain actions of the ASME B5 Committee may be published as Cases. Cases are published on the ASME Web site under the Committee Pages at <http://cstools.asme.org/> as they are issued.

Errata to codes and standards may be posted on the ASME Web site under the Committee Pages to provide corrections to incorrectly published items, or to correct typographical or grammatical errors in codes and standards. Such errata shall be used on the date posted.

The Committee Pages can be found at <http://cstools.asme.org/>. There is an option available to automatically receive an e-mail notification when errata are posted to a particular code or standard. This option can be found on the appropriate Committee Page after selecting "Errata" in the "Publication Information" section.

ASME is the registered trademark of The American Society of Mechanical Engineers.

This code or standard was developed under procedures accredited as meeting the criteria for American National Standards. The Standards Committee that approved the code or standard was balanced to assure that individuals from competent and concerned interests have had an opportunity to participate. The proposed code or standard was made available for public review and comment that provides an opportunity for additional public input from industry, academia, regulatory agencies, and the public-at-large.

ASME does not "approve," "rate," or "endorse" any item, construction, proprietary device, or activity.

ASME does not take any position with respect to the validity of any patent rights asserted in connection with any items mentioned in this document, and does not undertake to insure anyone utilizing a standard against liability for infringement of any applicable letters patent, nor assumes any such liability. Users of a code or standard are expressly advised that determination of the validity of any such patent rights, and the risk of infringement of such rights, is entirely their own responsibility.

Participation by federal agency representative(s) or person(s) affiliated with industry is not to be interpreted as government or industry endorsement of this code or standard.

ASME accepts responsibility for only those interpretations of this document issued in accordance with the established ASME procedures and policies, which precludes the issuance of interpretations by individuals.

No part of this document may be reproduced in any form,
in an electronic retrieval system or otherwise,
without the prior written permission of the publisher.

The American Society of Mechanical Engineers
Two Park Avenue, New York, NY 10016-5990

Copyright © 2013 by
THE AMERICAN SOCIETY OF MECHANICAL ENGINEERS
All rights reserved
Printed in U.S.A.

CONTENTS

Foreword		vi
Committee Roster		vii
Correspondence With the B5 Committee		viii
1	Scope.....	1
2	References	17
3	Nomenclature	17
4	Definitions	20
5	Environmental Specifications	33
6	Environmental Tests	35
7	Machine Performance.....	43
8	Machine Performance (Additional)	88
9	Test Equipment and Instrumentation	102
Figures		
4-1	The Six Basic Error Motions of an Axis of Rotation.....	21
4-2	Error Motion Polar Plot Showing a Polar Chart Center, a Least-Squares-Circle Center, and Error Motion Values About These Centers	24
4-3	An Example of a Structural Loop Showing a Workpiece, Spindle, Machine Bed, and Tool	31
6.2.1.4-1	Setup Showing Two Displacement Sensors Used to Measure the Environmental Temperature Variation Error (<i>ETVE</i>) Between a Nominal Tool Location and a Work Spindle	36
6.2.1.4-2	Setup Showing Three Displacement Sensors Used to Measure the Environmental Temperature Variation Error (<i>ETVE</i>) Between a Nominal Tool Location and a Work Spindle	38
6.2.1.4-3	Graph of Environmental Temperature Variation Error (<i>ETVE</i>) Data	39
6.2.1.6-1	Setup Showing Five Displacement Sensors Used to Measure the Environmental Temperature Variation Error (<i>ETVE</i>).....	39
7.2.3-1	Typical Setup for a Laser Interferometer.....	45
7.2.7-1	The Full Data Set for the Positioning Deviations of an Axis	48
7.2.7-2	Positioning Deviations of an Axis, Forward Direction Only	49
7.2.8-1	Periodic Error of a Linear Axis (Unidirectional)	50
7.3.1.1-1	Setup for Measuring Straightness Using an Electronic Indicator and a Mechanical Straightedge	51
7.3.1.2-1	Test Setup for Measuring Straightness Using a Taut Wire	52
7.3.1.3-1	Test Setup for Measuring Straightness Using an Alignment Laser.....	53
7.3.1.4-1	Typical Straightness Interferometer	53
7.3.2-1	Typical Plot Showing Straightness Data With the Straightness for a Particular Axis Clearly Labeled	54
7.4.1-1	Typical Setup for Measuring the Angular Error Motion (Yaw) of the Cross-Slide on a Group 1 Machine	55
7.5.2-1	Schematic for the Measurement of Angular Positioning Using an Indexing Table and a Laser Interferometer	56
7.5.2-2	Setup for Adjusting the Alignment of an Indexing Table and a Laser Angle Interferometer	56
7.5.4-1	A Polygon Mounted to a Spindle Axis	58
7.5.5-1	Typical Setup for Measuring the Angular Positioning Accuracy of a Rotary Axis Using an Angular Encoder	59

7.5.8.2-1	Typical Setup for Periodic Angular Error Measurement Using Mechanical Means.....	60
7.6.3-1	Test Setups for Measuring Spindle Error Motions in the Case of Fixed Sensitive Direction.....	62
7.6.4-1	Test Setup for Measuring Spindle Error Motions in the Case of Rotating Sensitive Direction.....	64
7.6.4-2	Spindle Test Setup With an Eccentric Ball.....	65
7.7.2.1-1	Sensor Data From a Typical Spindle Thermal Warm-Up Test.....	67
7.7.2.1-2	Tilts of the Axis Average Line, Spindle Warm-Up Test.....	68
7.7.3.1-1	Path for Measuring Thermal Distortion Caused by Moving Linear Axes.....	69
7.7.3.2-1	Position Error Versus Time for a Typical Test for Thermal Distortion Caused by a Moving Linear Axis.....	70
7.7.4.1-1	Typical Results From a Composite Thermal Error Test.....	72
7.8.2.1-1	Setup for Measuring Squareness of the Cross-Slide to the Work Spindle Using a Mechanical Straightedge.....	74
7.8.2.1-2	Schematic Showing the Angles Involved When Measuring Cross-Slide Squareness to the Spindle Axis.....	74
7.8.2.1-3	Typical Data From a Cross-Slide Out-of-Squareness Measurement.....	75
7.8.2.2-1	Two Views of the Cylinder Used for Measuring Machine Out-of-Squareness and Parallelism.....	76
7.8.2.2-2	Part-Trace Test Past Centers to Determine Cross-Slide Squareness With the Spindle Axis.....	77
7.8.2.2-3	Typical Data From a Cross-Slide Out-of-Squareness Measurement by Part Tracing Past Center.....	77
7.8.2.3-1	Cylinder Reversal for Cross-Slide Squareness.....	78
7.8.3.1-1	Setup for Straightedge Rotation on a Vertical Spindle Lathe for Measuring Z-Axis Parallelism to the C-Axis.....	78
7.8.3.1-2	Setup for Straightedge Rotation on a Horizontal Spindle Lathe for Measuring Z-Axis Parallelism to the C-Axis.....	79
7.8.3.2-1	Z-Slide Parallelism Schematic Showing the Test Cylinder.....	79
7.8.3.2-2	Typical Data From a Parallelism Measurement Using the Turned Cylinder Method.....	80
7.8.4-1	Dual Straightness Measurement for Parallelism.....	81
7.8.4-2	Graphing of Both Straightness Measurements for Twice the Angle of Parallelism.....	81
7.8.4-3	Setup for Measuring Long-Range Parallelism of the Z-Axis in the Case of a Vertically Traversing Axis.....	82
7.9.2-1	Typical Setup for a 360-deg Ball Bar Test.....	84
7.9.2-2	Typical Results From a 360-deg Ball Bar Test.....	84
7.9.3-1	The Ball Bar Setup for the 190-deg Test on a Lathe.....	85
7.9.3-2	Typical Results From a 190-deg Ball Bar Test on a Lathe.....	85
7.9.4-1	Typical Ball Bar Setup for a 100-deg Test.....	86
7.9.4-2	Typical Results of a 100-deg Ball Bar Test.....	87
7.10.2-1	A Typical Plot of the Power Loss in the Spindle Idle Run Loss Test.....	88
8.2-1	Illustration of Angularity and Offset Between Two Axes of Rotation.....	89
8.2.1-1	Typical Setup for the Rim-and-Face Test.....	90
8.2.1-2	Setup for Measuring the Sag of a Pair of Indicators.....	90
8.2.2-1	Typical Setup for the Reverse Indicator Method.....	91
8.2.3-1	Rotation Axes Alignment Using an Optical Alignment Laser.....	92
8.2.4-1	Two-Sphere Setup for the Alignment of Two Rotation Axes.....	93
8.2.5-1	Schematic of the Measurement of Parallelism of the Z-Axis to the Axis of a Movable Tail Stock.....	93
8.2.5.1-1	Setup for Measuring Tail Stock Alignment Using the In-Feed (Z) Axis.....	94
8.3.1-1	Tool Holders Used for Tool-Change Repeatability.....	95
8.3.2-1	Example Tool Holders to Be Used for Turret Repeatability.....	96
8.4.2-1	Test Part for Determining the Location of a Tool-Setting System and Tool-Setting-System Drift.....	98
8.6.2-1	Approximate Location of Probed Points, Depending on Probe Configuration, When Measuring a Machined Test Part.....	100
8.6.3-1	Approximate Location of Probed Points, Depending on Probe Configuration, When Measuring a Test Sphere.....	101

Forms

1	Machine Description	2
2	Environmental Specifications Guidelines	4
3	Environmental Tests (Section 6)	6
4	Machine Performance (Section 7).....	7
5	Coaxiality of Axes of Rotation (Para. 8.2)	14
6	Subsystems Repeatability (Para. 8.3)	15
7	CNC Performance Tests (Para. 8.5)	16
8	Machine Performance as a Measuring Tool (Para. 8.6)	16

Tables

6.2.2.1-1	Specification Zones Derated Due to an Excessive Expanded Thermal Uncertainty	40
6.3.1-1	Performance Parameters Derated Due to Excessive Environmental Vibration	42
7.2.7-1	Typical Test Results (Test for Linear Axis up to 2 m)	47
7.2.7.9-1	Conversion Factors for Graphically Estimating Standard Uncertainty.....	50
7.7.4.3-1	Typical Presentation of Results From Composite Thermal Error Tests	72
7.9.5-1	Typical Results of a Ball Bar Test	87

Nonmandatory Appendices

A	Guide for Using the Draft Turning Center Standard	105
B	1-Day Test for Machine Performance	106
C	Thermal Environment Verification Tests.....	107
D	Seismic Vibration Verification Tests	109
E	Electrical Power Verification Tests	113
F	Machine Functional Tests	114
G	Machine Leveling and Alignment.....	116
H	Compliance and Hysteresis Checks.....	117
I	Laser and Scale Corrections	120
J	Drift Checks for Sensors, Including Lasers.....	121
K	The Part-Trace Test	124
L	Discussion of the <i>UNDE</i> and Thermal Uncertainty	125
M	Calculation of Uncertainties.....	130
N	Sign Conventions for Error Values.....	134