

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/ GJM- 21

SECTION I : IDENTIFICATION				
1. Name				
Present Past Other Name (if any):	: Kanaka Durga Temple, : :	Raulapali, Dist Ganjam		
2. Location				
LONGITUDE 84 ⁰ 48' 48" E	LATITUDE 19 ⁰ 29' 48" N	ELEVATION 152 ft		
Address	: Village (village code) Post : Antarigaon Tehsil:Purushottampur State : Orissa	Raulapali Via: Pandia District: Ganjam PIN: 761043		
Approach	Raulapali is situated at	of a granite hillock in the village a distance of 3 kms south of 5 kms from Jaugada, the soka.		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify):		
Other public buildings	Tomb, Madocidan	Note.		
Residential building Engineering structure	Open space and related	The temple has a rekha vimana and a pidha jagamohana of		
Bridge Tunnel Other engineering structure	structures Public square Park or garden Graveyard Baolis, Well Tank Cave	impoverished <i>Kalingan</i> order.		

4. Property Use				
ABANDONED / IN USE :				
Present	: Living temple, the presiding deity is the goddess six- armed Mahisasuramardini Durga.			
Past	: Worshipped			
5. Age (Source)				
PERIOD YEARS Precise date of Construction Completion	 During the Bhanja rule of ex-Ghumsar state. 19th century A.D. First half of the 19th century A.D. 			
Subsequent changes Destruction / Demolition	: :			
6. Ownership / Level of Protection	on			
C. Children P. Level of Floteette	SINGLE /MULTIPLE : Multiple			
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private	: Endowment Department Government of Orissa.			
Any other (Please specify) Name Address Phone 7. Association	: Temple Managing Trust : : :			
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	 : : Durga puja is celebrated here. : : Marriage, thread ceremony, etc are observed here. : Endowment Department Government of Orissa. : : Temple Managing Trust 			
Architectural Archaeological Historical Religious Any other (specify)	 ∴ Architectural ∴ On the basis of architectural feature and local information, the temple can be assigned to the first half of the 19th century A.D. 			

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting : Surroundings	,	Drawings (Attach extra sheet if necessary): No Rural setting		
oun ounum go	ı	Stand in Isolation Integral part of a Landscape / Complex Street / Complex :		
• Quantification Area Dimension (L x B x H)		10.50 mtrs x 5.00 mtrs x 9.80 mtrs(approximate height) (m / cm/ feet / inch)		
Number of Blocks Number of Storys		Two N.A.		
• Spatial Organization Orientation : Plan : Allocation of Spaces :	-	Facing towards east. The <i>vimana</i> and <i>jagamohana</i> are square on plan that stands over a platform of 0.90 mtrs high. 20.00 mtrs (L) x 35.00 mtrs (W)		
ARCHITECTURAL STYLE				
• Ornamentation Exteriors :	<i>l</i> (Decorated with architectural motifs like khakharamundis and pidhamundis enshrining images of mithuna, maithuna, divinities such as- Brahma, Mahisasuramardini Durga, Ganesa, Sivani, etc and deulacharinis and dopichhasimhas over the beki.		
Interiors : Movable Collections : * Any Other (specify) :	F \ -	Plain Visnu, six headed Kartikeya, Nandi The temple is <i>pancharatha</i> on plan and <i>panchangabada</i> in elevation.		
10. Construction Technology				
Structural System : Building Techniques : Material of Construction :	/ /	Rekha vimana and pidha jagamohana of impoverished Kalingan order. Ashlar dry masonry Khandolite stone and lime plaster is applied on the exterior surface.		
11. Condition Assessment				
In General Good / Fair :	F	=air		
✓ Sign of Deterioration Serious Deterioration Danger of Disappearance				

Lichen and mo	ess are noticed on the w	alls of the temple.
12. Threats to	the Property	
x	× × × × × × × × × ×	Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x
	SECT	ION III: REFERENCES
13. Reference	Sources (published an	d unpublished textual details)
1 2. 3.		
14. Photograp	hs: 34 nos	
		(attach list as in page 6, in case of multiple photographs)
Photo Referen	:	
15. Audio / Vi	deo	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	i :	(
16. Maps/Plan	s/Drawings	
17. Listers		
NAME :	Jaya Shankar Naik	NAME :
18. Reviewers	3	
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:

In Brief (Attach extra sheet if necessary):